

## BUILDING SAFETY CERTIFICATE

No. 141

Dated: 15.01.2023

Certified that the existing building **NORTH EAST PUBLIC SCHOOL ROWTA** at Bhalukmari, PO- Bhalukmari, Dist- Udalguri, BTR, Assam comprised of **1 (one) basement(s) and 2 (Two)** (upper floors) owned/occupied by **NORTH EAST PUBLIC SCHOOL ROWTA** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD, Building, Udalguri** on **15/1/23** in the presence of **John V.K (principal)** and that the building/premises is fit for occupancy upto classes **X.II** (X/ XII) with effect from **15/1/23** for a period of **25** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. **periodic repair and Maintenance.**
- 2.
- 3.
- 4.

Issued on **15/01/2023** at **Udalguri** by

\* Strike out whichever is not applicable.

Signature with Seal :

**Assistant Engineer, P.W.D. (Building)**  
**Udalguri & Baksaj District**  
**Special Building Division**  
**Udalguri, Assam**

Name : **KANKHAR MASHAHAR Y**

Designation : **ASSISTANT ENGINEER**


Name & Address of Department/ Office: **PWD (Bldg), Udalguri**

(Assistant Engineer & above officer of concerned Govt. Department only)

**Note:** This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

  
PRINCIPAL  
NORTH EAST PUBLIC SCHOOL, ROWTA

  
Manager  
North East Public School  
Rowta  
Date.....